
USER MANUAL

Description: Full motion monitor arm Model No: CTS301


Thanks for buying the product. Please read this manual carefully before you start installing.


Spec Data											
Į	KG	$ar{ar{\zeta}}$		*				NW	GW		厚度(mm) ness range
LCD Size	Weight Capacity	Height Adjust	Tilt	Swivel	Pivot	VESA	Packing Size	Net Weight	Cross Weight	Thru desk	Desk clamp
≦ 32″	2-9	250	-10°~ +90°	180° /360°	±90°	75×75	755*275*135	Inner:	Inner:	15-50	15-50
= 32	2-9	230	−10 ±90	100 / 300	±90	100×100					




Parts List						
No.	Image	Part No.	Quantity			
A			2			
В	[]E		1			
С	LOP		3			
D	*		1			
E			1			

Parts List				
No.	Image	Part No.	Quantity	
а		M4x16	12	
b		6#	1	
С		4#	1	
d			8	
е	d and a second	M8×80	1	
f			1	







- 1. Never overload it. Otherwise, it may cause damage to monitor or human body.
- 2.Please strictly follow the procedures in this manual for installation. Wrong installation may cause damage to product or human body.
- 3.Please use the tools and parts provided by us.Otherwise, it may cause damage to product.
- 4. Make sure you desk/table is strong enough to support the product and all its parts.
- 5. This product contains small parts. It will cause personal injury if swallowed. Please put them beyond the places where children can reach.
- 6. Please install monitor after assembling this product.
- 7. Please make sure your monitor is fixed properly before you adjust it.
- $8. \ \mbox{Please}$ don't disassemble or exchange the arm of this product arbitrarily.



